Version: 1.0.11305.15004

Date: 07/15/13

Known Issues

• Scanner control Software error is returned when trying to scan a page after no memory error. This error actually occurs while we are handling the no memory and it remains on the scan queue until a new pages is scanned. Fixing this issue will involve changing scanner behavior and will be a high risk to take at this stage of the project.

Fixes

ISIS-36787 Selecting Kodak i1120 Scanner While In Error Condition

Driver should not be re-loaded while scanner is in a bad state. We are now checking status before loading modules.